Service Instruction SI-0006

Technical Portions FAA Approved

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

Subject: Stall Computer Tuning Procedures

ATA-Code: 31-00

Labor: 6 hours

Effectivity: K007

Affected Model(s): E1000

Due: 4/16/2021

Compliance: Recommended ☒ Mandatory ☐

Recurrence: No

1 BACKGROUND AND PURPOSE:

A stall computer was replaced in aircraft K007 and requires tuning. This Service Instruction provides instructions for performing this tuning.

2 REFERENCES:

Epic E1000 Airframe Maintenance Manual, SK05000000 Rev B
Epic E1000 Wiring Manual, SK05000002 Rev -
Production Flight Test Manual, FTM-000 Rev G
Stall Protection System Checkout and Adjustment, SK31000002 Rev -

3 WARRANTY:

For aircraft under warranty, parts and labor will be covered by Epic Aircraft, LLC if the work is performed within the compliance period and at an Authorized E1000 Service Center.

4 TOOLS:

No.	Description	Qty	Epic Aircraft Supplied	Customer Supplied
1.	Common Hand Tools		☒	☐
2.	Stall Computer Breakout Box (SK100360)	1	☒	☐
3.	Lift Computer Voltage Test Harness (DWK17310001)	1	☒	☐
4.	Safe Flight Force Gauge Applicator	1	☒	☐
5.			☐	☐

5 PARTS/MATERIALS:

No.	Part Number	Description	Qty	Epic Aircraft Supplied	Customer Supplied
1.	N/A			☐	☐
2.				☐	☐

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701

Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com



Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

6 INSTRUCTIONS:

Test Setup
For the following tests, it will be necessary to install the Lift Computer Voltage Test Harness as described in the previous figure. Gain access to the stall computers under the passenger floor in accordance with the Airframe Maintenance Manual.

Test Procedures
Perform the following tests with the aircraft in the heavy forward configuration and with the Lift Computer Voltage Test Harness installed. From trim speed decelerate at approximately 1 knot per second. Note the speed of shaker activation. The stall warning shaker shall activate at least 5 knots prior to the pusher. It shall not activate so early as to provide nuisance warnings during normal takeoff operations. Verify the Red warning “STICK SHAKER” CAS message appears with an aural “STALL-STALL-STALL”.

Continue decelerating at 1 knot per second until the pusher activates as evidenced by nose down pitching. Verify the Red warning “STICK PUSH” CAS message appears with an aural “PUSH-PUSH-PUSH”.

Verify the AoA indications at each flap position for the shaker and pusher activation. Shake = 0.76 ± 0.04, Push = 0.92 ± 0.04.

NOTE:
Incorrect deceleration can produce incorrect shake and push values.

Requirements
Stalls shall be conducted in the following configurations:

1. Flaps UP, Gear UP, High idle – Trim 127 KIAS, Shaker speed margin 5-8 KIAS from push, Push speed margin 5-8 KIAS from stall.
2. Flaps T/O, Gear UP, High idle – Trim 125 KIAS, Shaker speed margin 6-9 KIAS from push, Push speed margin 6-8 KIAS from stall.
3. Flaps FULL, Gear DN High idle- Trim -102 KIAS, Shaker speed margin 10-11 KIAS from push, Push speed margin of at least 2 KIAS from stall not to exceed 68 KIAS.

Natural Stall speeds were determined for this aircraft (K007) during production flight test, values provided below for reference.

- Flaps Up, Gear Up, 78 KIAS
- Flaps T/O, Gear Up, 73 KIAS
- Flaps Full, Gear DN, 66 KIAS

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

Tuning Procedures

When additional tuning is deemed necessary the following steps are required:

1. Connect a breakout box to the lift computer to be adjusted. Monitor voltage from the lift transducer using positive lead on pinout 22 and negative lead on pin 23.
2. Connect the Force Gram Applicator (FGA) to the appropriate lift transducer.
3. Disconnect the shake motor to avoid unnecessary vibrations.
4. With the acceptable tool, place the aircraft in Weight **Off** Wheels mode.
5. For the flap condition requiring adjustment (if tuning flaps full an air data test set is required):
   a. Adjust the appropriate potentiometer an amount deemed reasonable (an approximate amount is -0.15 volts per +1 knot). A clockwise turn will apply negative volts, and a counterclockwise turn will apply positive volts, see diagram below.
   b. Reverify that the push or shake becomes active at the new voltage setting using the FGA to approach the push or shake.
   c. Repeat the previous two steps as needed for the other flap settings.
   d. Record the new values.

	VDC Left		TG Left		VDC Right		TG Right	
Flaps	**$VOLT_{PSH}$**	**$VOLT_{SH}$**	**TG_{PSH}**	**TG_{SHK}**	**$VOLT_{PSH}$**	**$VOLT_{SH}$**	**TG_{PSH}**	**TG_{SHK}**
UP								
T/O								
FULL								

6. Reconnect the shake motor.
7. Flight test the new lift computer settings. If necessary repeat steps 1-6 as required.



Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

7 WEIGHT AND BALANCE:

N/A

8 PUBLICATIONS AFFECTED:

N/A

9 RECORD COMPLIANCE:

Make appropriate entry in airplane maintenance records.

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

Flight Deck Card

Action/Setup	Expected Result	Actual Result/Notes	P/F
Stick Shaker/Pusher Stalls			
Flap UP, Gear UP, Idle, Trim 127 KIAS	Shaker 5-8 knots of margin from push AoA 0.72 to 0.80 Aural Alert “STALL STALL STALL” and Red “STICK SHAKER” CAS Pusher 5-8 knots of margin from stall AoA 0.88 to 0.96 Aural Alert “PUSH PUSH PUSH” and Red “STICK PUSH” CAS	Shaker Pusher AoA	
Flap T/O, Gear UP, Idle, Trim 125 KIAS	Shaker 6-9 KIAS of margin from push AoA 0.72 to 0.80 Aural Alert “STALL STALL STALL” and Red “STICK SHAKER” CAS Pusher 5-8 knots of margin from stall AoA 0.88 to 0.96 Aural Alert “PUSH PUSH PUSH” and Red “STICK PUSH” CAS	Shaker Pusher AoA	
Flap FULL, Gear DN, Idle, Trim 102 KIAS must have 2 knot margin over aero stall	Shaker 10-11 knot of margin from push AoA 0.72 to 0.80 Aural Alert “STALL STALL STALL” and Red “STICK SHAKER” CAS Pusher 2 knots of margin from stall AoA 0.88 to 0.96 Aural Alert “PUSH PUSH PUSH” and Red “STICK PUSH” CAS	Shaker Pusher AoA	

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

Appendix A: Compliance Letter

Please complete and mail this form to Customersupport@epicaircraft.com

This is to certify that I have completed the work in accordance with the Epic Aircraft, LLC Service Instruction.

Aircraft Owner Information:
Date: _____ Aircraft Serial Number: _____ Aircraft Reg. Number: _____ Owner's Name: _____
Maintenance Entity Information
Name of Shop Performing the work: _____ Name of Person(s) Performing inspection and/or work: _____ Phone Number: _____ Email: _____