Service Advisory SA-0013

Technical Portions FAA Approved

Epic Aircraft, LLC ◆ 22590 Nelson Road ◆ Bend OR 97701
Phone: 541-318-8849 ◆ Fax: 541-382-5125 ◆ Web: www.epicaircraft.com

Subject: Progressive Inspection Program Update

ATA-Code: 5-30

Effectivity: K003 and On

1 BACKGROUND AND PURPOSE:

Operator feedback on the E1000 Progressive Inspection Program identified a need to improve clarity of the Pratt & Whitney engine inspection requirements. Chapter 5-30 of the E1000 Aircraft Maintenance Manual (AMM) has been revised to more clearly identify the engine inspection requirements applicable throughout the Progressive Inspection Program.

This Service Advisory has been issued to inform owners and operators of this revision and to provide awareness of the updated AMM content.

2 REFERENCES:

Epic E1000 Aircraft Maintenance Manual, P/N SK05000000.

3 INFORMATION:

Owners, operators, and maintenance providers utilizing the E1000 Progressive Inspection Program should review Chapter 5-30 of Revision K, or later, of the Epic E1000 Aircraft Maintenance Manual, P/N SK05000000. The revised program provides additional clarification regarding the applicable Pratt & Whitney engine inspection requirements.

Progressive inspections should be performed using the current revision of the AMM and the applicable referenced engine maintenance instructions.